SERVICE REPORT

SR 2072

Brighter Demonstration Company

24 Example Road
Newcastle NSW 2300 · Fictional example
ABN 12 345 678 901 | Phone 02 5550 0100

Service work completed

CUSTOMER PURCHASE ORDER / REFERENCE

POOL-PO-7642

CUSTOMER & WORK SITE

Northside Pool & Trade
Warehouse receiving dock
8 Example Street
Newcastle NSW 2300

VISIT DETAILS

Technician: Jamie Example
Completed: 6 Oct 2026, 2:30 pm (Sydney time)
Internal job reference: BM 2072

WORK COMPLETED

Pool clean and filter replacement

Fictional demonstration. Cleaned the pool, replaced the filter cartridge and tested circulation. Water flow restored and the work area left clean.

RECORDED LABOUR

90 minutes across 1 visit

CUSTOMER ACKNOWLEDGEMENT

Name recorded by technician: Sam Example

Acknowledgement records the name provided to the technician; it is not a captured signature.

PRODUCTS & MATERIALS SUPPLIED

Product / pack	Quantity used	Unit
Replacement filter cartridge **Single filter**	**1**	each

COMPLETED CHECKS

Completed: Filter fitted

Completed: Flow checked

Completed: Work area left clean

Service completion record - not a tax invoice. Charges are reviewed separately. Questions? Contact Brighter Demonstration Company on 02 5550 0100.